

# Lanco Inspects LLC

Residential Property Inspection/Estimates

## Radon Testing Results

Roberta Smith  
#1194 CoLechii Drive  
Bridge New Jersey

9/25/06

Re: #86 Wildflane Lane  
New Castle, De

We have completed testing the above mentioned property for radon emissions.

Testing was completed by using the "Safety Siren Pro Series Radon Gas Detector and air absorption test #3899944 with results provided by "Radon.com" ...

1. Gas Detector. 2.0 pCi/L per liter
2. Air Absorption 2.2 pCi/L per liter

All results are measured in pCi/L per liter and are below the recommended exposure limit of 4.0 pCi/L

Treatment for radon gas emissions is not recommended

Insurance/warranty information available upon request.

Richard L Hiddemen

[Lancoinspects@aol.com](mailto:Lancoinspects@aol.com)  
<http://www.weseeit4u.com/>  
N.C.C. #GC1764

D.D.A. #06-444

Wilmington, Delaware  
302-239-4061  
De. # 1992105842